



Product Change Notification - SYST-30YQVB830

Date:

02 Sep 2019

Product Category:

Wireless Modules

Affected CPNs:**Notification subject:**

Data Sheet - MRF89XA Ultra-Low Power, Integrated ISM Band Sub-GHz Transceiver Data Sheet

Notification text:

SYST-30YQVB830

Microchip has released a new Product Documents for the MRF89XA Ultra-Low Power, Integrated ISM Band Sub-GHz Transceiver Data Sheet of devices. If you are using one of these devices please read the document located at [MRF89XA Ultra-Low Power, Integrated ISM Band Sub-GHz Transceiver Data Sheet](#).

Notification Status: Final**Description of Change:** The following is the list of modifications:

- 1) Updated RESVREG and RSTSREG register positions in Figure 2-18
- 2) Updated Bit 3 (ENRIRQS) description in Section 2.15.2 "FIFO TRANSMIT PLL AND RSSI INTERRUPT REQUEST CONFIGURATION REGISTER DETAILS"
- 3) Updated Sleep mode current value from 1 μ A to 2 μ A in Section 3.13 "Battery Power Management Configuration Values"

Impacts to Data Sheet: None**Reason for Change:** To Improve Manufacturability**Change Implementation Status:** Complete**Date Document Changes Effective:** 02 September 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A**Attachment(s):**

[MRF89XA Ultra-Low Power, Integrated ISM Band Sub-GHz Transceiver Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

MRF89XA-I/MQ

MRF89XAM8A-I/RM

MRF89XAM8AT-I/RM

MRF89XAM9A-I/RM

MRF89XAM9AT-I/RM

MRF89XAT-I/MQ