

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

EOL/PCN#25-058

NOTIFICATION DATE: October 7, 2025

MODELS AFFECTED

List of affected models on page 2

EXTENT OF CHANGE:

Discontinuation of listed models

EFFECT OF CHANGE:

Obsolescence of series of models. Contact Application Dept at apps@minicircuits.com for alternative solutions

REASON FOR CHANGE:

After careful consideration, a business decision was taken to end of life the listed models. Contact Sales Dept at Sales@minicircuits.com if you require further information.

EFFECTIVE DATE OF CHANGE:

Immediate, Last Time Buy availability is based on existing inventory. Contact your Account Manager or sales@minicircuits.com for availability

QUESTIONS?

[PLEASE CONTACT US.](#)

PRODUCT CHANGE NOTICE

PCN Form (D4-E000-73)

Affected Models	
CCC-2G42G53K0+	RFE-3G33G7100+
CCC-2G42G53K01+	RFE-3G33G7100X+
CCC-2G42G58K2+	RFE-5G86G7800+
COM-2G42G51K0+	RFE-G11G136K0+R
COM-2G42G53K0+	RFE-G49G510K9+
COM-2G42G53K1+	RFG-13M14MS01+
COM-2G42G56K0+	RFK-2G42G5050+
COM-2G42G56K0A+	RFS-1M92M11K0X+
COM-2G42G56K0+	RFS-2G42G5020X+
COM-2G42G58K0+	RFS-2G42G5050+
COM-2G42G58K1+	RFS-2G42G5050X+
COM-5G86G7800+	RFS-2G42G51K0+
COM-G11G136K0+	RFS-3G33G7100X+
COM-G90G9316K+	RFS-G43G44250X+
COM-G90G9316K0+	RFS-G90G93750+
COM-G90G9320K+	RFS-G90G93750W+
COM-G90G9320K0+	RFS-G90G93750X+
COM-G90G935K0+	RFX-2G42G5005+
COM-G90G936K0+	RFX-2G42G50W5+
COU-2G42G5040+	RPX-3P20832180
COU-2G42G5045+	RPX-3P20832500+
HSK-2425-250+	SPL-2G42G50W4+
HSK-2G42G5050+	SPL-2G42G50W5+
HSK-G90G93750+	SPL-G11G13020+
ISC-2425-25+	TER-2G42G56K0+
ISC-2425-27+	ZHK-2425-250+
RFE-24M30M075X+	ZHL-2425-250+
RFE-24M30M1K7X+	ZHL-2425-250X+