




Product Change Notification (PCN)

PCN Number	502863	Date Issued	September 28, 2017
Reason for Change	Supplier Change		
Change Type Description	This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change.		
Reason for Short Notice	Special Request		
Assessment of Change	Passed FAI		
Internal Molex Qualification Date	August 30, 2017		
Sample Availability Date (Changed Part)	August 30, 2017		
Planned Implementation Date	December 01, 2017		
Method of Identifying Change	Factory order number		

Before Change

Impacted Products Pictures



After Change

Overview

- Molex CD will have the copper strip shortage issue at the start of Dec. 2017, need to add another supplier to ensure continuity of supply
- Product Impact
 - No impact to fit, form and function.
- Part Number Impact
 - 78720-0001
 - 78719-0001
 - 78758-0001, 78758-0002
 - 78810-0001
- FAI and samples available upon request



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to
pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502863**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com