




Product Change Notification (PCN)

PCN Number	505353	Date Issued	February 14, 2018
Reason for Change	Change to Product		
Change Type Description	<p>This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.</p>		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	February 15, 2018		
Sample Availability Date (Changed Part)	February 15, 2018		
Planned Implementation Date	August 10, 2018		
Method of Identifying Change	Date code		

Before Change



- Originally 172952xx02 was white and now will be black.
- Series number 172953xx02 was black and now will be white.

After Change

- Overview**
- Due to contamination of the white receptacles we are changing the color of resin on series 172952 and 172953. Originally 172952xx02 was white and now will be black. Series number 172953xx02 was black and now will be white.
 - Product Impact
 - It is a running change, no impact to fit, form or function.
 - Part Number Impact
 - See attached impacted parts list
 - Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:505353**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com