




Product Change Notification (PCN)

PCN Number	508845	Date Issued	September 01, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	Dimension analysis		
Internal Molex Qualification Date	May 08, 2020		
Sample Availability Date (Changed Part)	May 08, 2020		
Planned Implementation Date	September 01, 2020		
Method of Identifying Change	Factory order number		

Before Change

After Change

Before and after change



Overview

- We are changing the sub-product element form in order to meet our product conformance;
 - A sub-product element known as a metal angle plate is getting changed. This metal angle plate was sticking to the hoods of the connector and was getting pressed in the current design. This is undesirable. Cutouts for reverse use are added. Change of the outer geometry to enable reverse application in the connector is also enabled.
- Product Impact
 - There is impact to form/appearance of the product
 - No impact on Function and Fit
- Part Number Impact
 - See attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508845**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com