




# Product Change Notification (PCN)

PCN Number	508976	Date Issued	June 03, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Assessment of Change	First article inspection		
Internal Molex Qualification Date	January 18, 2021		
Sample Availability Date (Changed Part)	January 18, 2021		
Planned Implementation Date	January 18, 2021		
Method of Identifying Change	Product made after planned implementation date can contain the change		

Before Change

- Before the change. Tape present between assembly and inner jacket




After Change

## Overview

- After removal of PET tape over assembly, between cores and inner jacket.

- Product Impact
  - Profinet Cable
  - no impact to fit, form or function



- Qualification Reports and samples available upon request after the date shown above and at first production of purchase order.



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508976**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)