



Product Change Notification

Date Issued :	December 16, 2022	PCN Number :	512731
Reason for Change :	Change Supplier		
Description of Change :	Current vendor flame retardant issues lead to delayed delivery and not enough capacity to support orders. Need add alternative source to ensure orders delivery on time. No changes will be made to product as part of this change.		
Reason for Short Notice :	Supplier Constraints		
Assessment of Change :	First Article Inspection		
Planned Implementation Date :	January 31, 2023		
Sample Availability Date:	November 25, 2022		
Internal Molex Qualification Date :	November 25, 2022		
Last date to request Samples by Customer :	December 30, 2022		
Traceability Code Markings / Date :	Date code		

Before Picture

■ Change description:

- ❑ Current vendor flame retardant issues lead to delayed delivery and not enough capacity to support orders. Need add alternative source to ensure orders delivery on time.
- ❑ This change comes from the supplier of our raw material. The wire will be the same datasheet only with different printing marking.

- **Purpose of the change:** to prevent material shortage and prevent customer's delivery delay.

After Picture

Overview

- Product Impact
 - No impact to fit, form or function.
 - They are pin-to-pin replacement.

- Part Number Impact
 - see attached impacted parts list.

- Qualification reports and samples available upon request after the date shown above.

- Shipment can be arranged upon request before the planned implementation date after the internal qualification done and customer approval received.

RELEASED

You may address inquires regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:512731
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 512731** " in the e-mail Subject line for faster response.

[Molex, LLC](#)
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com