



Product Change Notification

Date Issued :	October 28, 2024	PCN Number :	516130
Reason for Change :	Change to Product		
Description of Change :	This notification is to inform you of the correction of an error in the SD for the part(s) on the attached list. For details, please see below.		
Assessment of Change :	No change to parts - Form/Fit/Function		
Planned Implementation Date :	April 28, 2025		
Customer Sample Availability Date:	October 28, 2024		
Last date to request Samples by Customer : October 28, 2024			
Please note if Samples are not requested as per Customer Samples Request date, it may take additional 4-6 weeks to arrange Samples.			
Traceability Code Markings / Date :	No special marking on the product or packaging		

Before Picture

Change Objectives

Correction of error for SD-503480-002 PSD 001

Incorrect (current rev.E3 drawing)

NOTES

1. IN THE PACKAGE, PART NO.503480-**09 DETAILED DIMENSIONS.
REFER TO SD-503480-001
2. NUMBER OF CONNECTORS : 3000PCS/REEL

380	20.2	40.4	44	-	-	44	503480-4000	40
							503480-3800	38
							503480-3600	36
							503480-3400	34
330	14.2	28.4	32	-	-	32	503480-3200	32
380							503480-3000	30
							503480-2800	28
							503480-2600	26
							503480-2400	24
							503480-2200	22
							503480-2000	20
							503480-1800	18
							503480-1700	17
							503480-1600	16
							503480-1400	14
							503480-1200	12
							503480-1000	10
							503480-0800	8
							503480-0600	6
F	E	D	C	B	A	TAPE WIDTH	ORDER NO.	CIRCUIT

Correct (will updated drawing to rev.F)

NOTES

1. IN THE PACKAGE, PART NO.503480-**09 DETAILED DIMENSIONS.
REFER TO SD-503480-001
2. NUMBER OF CONNECTORS : REFER TO TABLE

4500 PCS	380	20.2	40.4	44	-	-	44	503480-4000	40
								503480-3800	38
								503480-3600	36
								503480-3400	34
3000 PCS	330	14.2	28.4	32	-	-	32	503480-3200	32
4500 PCS	380							503480-3000	30
								503480-2800	28
								503480-2600	26
								503480-2400	24
								503480-2200	22
								503480-2000	20
								503480-1800	18
								503480-1700	17
								503480-1600	16
								503480-1400	14
								503480-1200	12
								503480-1000	10
								503480-0800	8
								503480-0600	6
NUMBER OF CONNECTORS	F	E	D	C	B	A	TAPE WIDTH	ORDER NO.	CIRCUIT

- This is just a drawing modification.
- The product packaging quantity does not change.

Molex Confidential Information
© Molex, LLC - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



After Picture

Change Overview

- **Changes:**

- Correct error for SD-503480-002 PSD 001.
- SD-503480-002 PSD 001 will be updated from rev. E3 to rev. F.

- **Reason:**

- Correction of error.

- **Affected part numbers:**

- 503480 series (503480**00)

- **Product Impact:**

- No impact to fit, form, function of product because no change the product itself.
- This is just correcting the drawing.

Molex Confidential Information
© Molex, LLC - All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.

molex

RELEASED

You may address inquiries regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?subject=PCN_Notification:516130
or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 516130** " in the e-mail Subject line for faster response.

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL (800) 786-6539
www.molex.com