



Product Change Notification

Date Issued :	December 15, 2024	PCN Number :	516164
Reason for Change :	Change Supplier		
Description of Change :	This notification is to inform you that the sealing liquid used in 505476 series and 214250 series will be changed to PFAS free. Please refer to the following for details.		
Assessment of Change :	Reliability Test Report/s		
Planned Implementation Date :	June 15, 2025		
Customer Sample Availability Date:	December 16, 2024		
Last date to request Samples by Customer :	January 16, 2025		
Please note if Samples are not requested as per Customer Samples Request date, it may take additional 4-6 weeks to arrange Samples.			
Traceability Code Markings / Date :	Lot information on label		

Before Picture

Change Overview: Sealing liquid change

- **Sealing liquid is applied to this PN to avoid corrosion. Currently we are using fluorine sealing liquid, but we will change to PFAS free sealing liquid to reduce the environmental concern.**
- **Product Impact**
 - No impact to fit, form or function
- **PPAP and samples available upon request.**

Affected parts

Molex Product	Part Name
505476 / 214250 series	0.4BB CONN.RB PLUG

1 Molex Confidential Information
© Molex, LLC – All Rights Reserved. Unauthorized Reproduction/Distribution is Prohibited.



You may address inquires regarding this PCN by clicking on the below link
mailto:pcn_coordinator@molex.com?Subject=PCN_Notification:516164
 or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification : **PCN Notification: 516164** " in the e-mail Subject line for faster response.

[Molex, LLC](#)
 2222 Wellington Court
 Lisle, IL 60532
 TEL (800) 786-6539
www.molex.com