

Change Notice

SW Series

Deletion of Factory Code on SW3006A/U Case



Type of Change:

- ☐ Engineering ☐ Part Number
☐ Product ☒ Appearance

The SW Series rocker SW3006A/U will have a change to the printing on the case. Currently, the switch case has a UL marking and a factory code of 011. This will be revised to the same UL marking but without the numeric code. This change will effect both standard and custom models of SW3006A/U. The following table illustrates the differences before and after the revisions.



SW3006A/U Rocker

Before Change	After Change
	

Notes

This change will effect only SW3006A/U in the SW Series Rockers.

There will be no change to the country of origin (where switches are manufactured).

Contact factory if more details are needed.

Effective Date

Changes to SW3006A/U will be effective November 2015.

NKK
SWITCHES

<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

2015/07/23 Engineering Department