

PRODUCT CHANGE NOTIFICATION

Product Category SAFETY PTD **20230815-1**

Product Group ID AND SAFETY

ISSUE DATE: 15-Aug-23

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

Due to lack of unit sales, VeriSafe Access Control components will be discontinued. Solid state contacts integral to VeriSafe units will be unchanged.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	11	15

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-CSV@panduit.com	CHINA: 400-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) SGP-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free) BRA-custservice@panduit.com	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free) MEX-customerservice@panduit.com	OTHER LA COUNTRIES: Phone USA 1-708-532-1800 TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA EMEA-CustomerServices@panduit.com	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

FORM C2-1003 DATE: 06APR21 APPR: MURILLO

To add a contact or to unsubscribe, please send an email to:

PCN@panduit.com

FORM C2-1003 DATE: 06APR21 APPR: MURILLO
WWW.PANDUIT.COM

FORM C2-1003 DATE: 06APR21 APPR: MURILLO
WWW.PANDUIT.COM

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

Replacement Type Definition

DIRECT REPLACEMENT

Exact same part in a different package or has any other update that doesn't change the product itself

COMPATIBLE

The replacement part is different in some way that allows it to be used for some applications, but it is not the same part. The difference can be in color, size, material, or performance (like *CAT5 to CAT6*), etc.

COMPLEX

The replacement part(s) are too dissimilar to assume it can easily replace the discontinued part, however Panduit can offer a replacement which may be used in certain applications. Customer Experience should be contacted.

NO REPLACEMENT

No replacement product is available

e size,
change

a way
e
rt. The
rial, or
etc.

nilar to
ntinued
a
ertain
ould be

ole.