

## PRODUCT / PROCESS CHANGE INFORMATION

### 1. PCI basic data

1.1 Company		STMicroelectronics International N.V
1.2 PCI No.		ADG/17/10606
1.3 Title of PCI		Packing Shipment (Flexiwatt): Change of tube termination
1.4 Product Category		see list
1.5 Issue date		2017-12-12

### 2. PCI Team

2.1 Contact supplier	
2.1.1 Name	ROBERTSON HEATHER
2.1.2 Phone	+1 8475853058
2.1.3 Email	heather.robertson@st.com
2.2 Change responsibility	
2.2.1 Product Manager	Lorenzo MOIOLI
2.1.2 Marketing Manager	Valeria SCARCELLI
2.1.3 Quality Manager	Marcello Donato MENCHISE

### 3. Change

3.1 Category	3.2 Type of change	3.3 Manufacturing Location
General (Logistic)	3rd level packaging materials (shipment carton, sealing tape...)	ST Shenzhen (China)

### 4. Description of change

	Old	New
4.1 Description	See enclosed details	See enclosed details
4.2 Anticipated Impact on form,fit, function, quality, reliability or processability?	No Impact	

### 5. Reason / motivation for change

5.1 Motivation	To improve packing robustness
5.2 Customer Benefit	SERVICE IMPROVEMENT

### 6. Marking of parts / traceability of change

6.1 Description	Datacode
-----------------	----------

### 7. Timing / schedule

7.1 Date of qualification results	2017-12-01
7.2 Intended start of delivery	2017-12-03
7.3 Qualification sample available?	Upon Request

### 8. Qualification / Validation

8.1 Description	10606 5W and Details.pdf		
8.2 Qualification report and qualification results	Available (see attachment)	Issue Date	2017-12-12

### 9. Attachments (additional documentations)

10606 Public product.pdf
10606 5W and Details.pdf

10. Affected parts		
10. 1 Current		10.2 New (if applicable)
10.1.1 Customer Part No	10.1.2 Supplier Part No	10.1.2 Supplier Part No
	E-TDA7384A	
	E-TDA7385	
	E-TDA7386	
	E-TDA7560	
	E-TDA7566	
	STPA001	
	STPA003CD-48X	
	STPA003OD-4WX	
	STPA008-4WX	
	STPA008-QIX	
	TDA7381	
	TDA7385H	
	TDA7387EP	
	TDA7388	
	TDA7388A	
	TDA7560H	
	TDA75610S-48X	
	TDA75610SEP-HLX	
	TDA75613LV	
	TDA7562	
	TDA7562B	
	TDA7563A	
	TDA7563AH	
	TDA7563B	
	TDA7563BH	
	TDA7569BLV	
	TDA7575B	
	TDA7577BLV	
	TDA7801	
	TDA7802	
	TDA7850	
	TDA7850A	
	TDA7850AH	
	TDA7850H	
	TDA7851A	
	TDA7851F	
	TDA7868	

**IMPORTANT NOTICE – PLEASE READ CAREFULLY**

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2016 STMicroelectronics – All rights reserved



## Packing Shipment (Flexiwatt): Change of tube termination and plug

### WHAT:

Please be informed that we are going to change tube termination and plugs

Current



New



### WHY:

To improve packing robustness against risk of ICs jamming and ICs drop down in case of shake or tube deformation

### WHO:

All the products delivered in tubes (see detailed list)

### WHEN:

Starting from December 2017

### WHERE:

ST Shenzhen (China)