



520 Park East Blvd., New Albany, IN 47150 U.S.A
(812)-944-6733 / 1-800-SAMTEC9

Product Change Notification

1. ECR #: 207910
Notification #: 600

2. Date of Announcement: October 11, 2021

3. Series:

- ECUO - OPTICAL FIREFLY ASSEMBLY
- ETUO - ETUO

4. Part #'s Affected

- ECUO-B04-14-XXX-X-X-X-XX
- ECUO-B04-14-XXX-X-X-X-X
- ETUO-B04-10-XXX-X-X-X-XX
- ETUO-B04-10-XXX-X-X-X-X

5. Description of Change:
Firmware revision change to 00.14.16

6. Method of Identifying Change
Lower memory bytes 69-71 now read: 0x000E10

7. Reason for Change:
The firmware update is for internal manufacturing purposes only and will not affect the behavior of the product.

8. Impact of Change on Form, Fit, or Function:

- Function - Memory map change for firmware revision

9. Projected Implementation Date: October 11, 2021

Disclaimer

Please review the change notification details listed above for specific information regarding the nature and timing of the change. While Samtec has taken precautions to ensure this change is not detrimental to your application, each application can be unique and therefore customers should consider the effect of the change on their specific application.

Samtec has taken efforts to ensure that all users of this product who have requested change notifications have been informed. However, you should assume that this is the only notification that will be sent and you, as the recipient, must determine how to communicate this information to your organization(s) and customer(s) as appropriate. If you wish to opt out of receiving Samtec Product Change Notification emails, please contact CustomerECN@samtec.com. Due to technical progress, specifications are subject to change without notification and it is recommended to provide an alternative contact when opting out.

Please contact Samtec at CustomerECN@samtec.com for any questions related to this change.