

Date: April 21, 2025

PCN- 28735

Product Change Notification

Change Title:

IMPROVED POWER PLUGS - SLEEVE LENGTH

Product (s) Affected:

760HZ 765Z 760KHZ 765KHZ 761KSZ12 767KSZ12 S761KSHZ12 767KZ
760Z S760HZ 760KZ 765KZ 761KSZ15 767KSZ15 S761KSHZ15 768KZ
760ZF S760Z 762KZ S760KHZ 761KSZ17 767KSZ17 S761KSHZ17 S761KHZ
762Z S760ZF 763KZ S760KZ S761KSZ12 761KSHZ12 761KHZ S761KZ
762ZF S765HZ S765KHZ S761KSZ15 761KSHZ15 761KZ S766KHZ
763Z S765Z S765KZ S761KSZ17 761KSHZ17 766KHZ S766KZ
765HZ 766KZ 860Z 865Z

Reason for Change:

INSULATOR IS RECESSED IN PLUG SLEEVE. PLUG SLEEVE CAN SHORT TO BASE OF CENTER PIN IN MATING JACK.

Description of Change:

REDUCE THE LENGTH OF THE SLEEVE PORTION OF THE PLUG FINGER TO ALLOW THE INSULATOR TO PROTRUDE.

Estimated Schedule of Change:

IMMEDIATE

Customer Acknowledgement Form

(To be filled out by the customer and returned to Switchcraft)

The indicated Customer Notification letter was received and acknowledged by the undersigned authority.

Name: _____

Signature

(Electronic Signature is acceptable)

Print

Company: _____

Location: _____

Title: _____

Date: _____

Please return the signed PCN form to the attention of:

Switchcraft Customer Service Department

kmoricette@switchcraft.com

FAX: 773-792-2129