

November 29, 2019

Product Information

Updated CSA marking for EPCOS varistors

Due to updated CSA standard, the marking will be changed on EPCOS varistors and labels that are produced from October 1, 2019.

Affected are the B721*, B722*, B723* and B726* series of varistors.

For an interim period shipments can include varistors with old and new markings.

Affected products

Ordering code	Marking on varistor	Marking on label
B72107*		√
B72110*	√	√
B72114*	√	√
B72120*	√	√
B72205S*/U*		√
B72207S*/U*		√
B72210S*/P*/U*/X*	√	√
B72214S*/P*/U*/X*/Q*/T*/F*	√	√
B72220S*/P*/U*/X*/Q*/T*	√	√
B72225*	√	√
B72232B*/M*	√	√
B72240B*/L*/M*	√	√
B72241L*/M*	√	√
B72242L*/M*	√	√
B72250L*	√	√
B72260B*	√	√
B72280B*	√	√
B723*	√	√
B72650*		√
B72660*		√

This change will have no effects on form, fit, function, quality, reliability and lead-times of the affected products.

TDK Electronics AG



Rosenheimer Strasse 141 e, 81671 Munich · Post: P.O.Box 80 17 09, 81617 Munich, Germany
 Headquarters: Munich · Commercial register of the local court (Amtsgericht): Munich HRB 127250
 Chairman of the Supervisory Board: Dr. Werner Faber
 Management Board: Joachim Zichlarz, Chairman · Joachim Thiele · Dr. Werner Lohwasser
www.tdk-electronics.tdk.com



Varistors, CeraDiodes
 Internal / External

191129VAR1e

November 29, 2019

Change of marking

CSA marking on varistors	
Current	New
	

CSA marking on labels	
Current	New
	

Contact Anthony Yu, PPD VAR PM, Zhuhai

Customers are asked to address inquiries directly to their sales contacts.