



Product Change Notification

Current Date: 29-Jun-2016

TE Connectivity

Product Change Notification: P-16-013196

PCN Date: 27-JUN-16

Customer: DISTRIBUTOR NA (66666661)

Location: NO CITY PROVIDED

Agreement: 120513180001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Heavy Duty Connectors

Description of Changes

Manufacturing location change. Following Part Numbers will be transferred from TE Trutnov, Cz to TE Bydgoszcz, Poland. The new location is ISO 9001 and TS 16949 certified and will implement / certify to IRIS. The TS certification gives the new location an excellent foundation to reach the IRIS requirements. We are following the IRIS implementation protocol which demands that as part of the certification process the manufacturing location must run production for 3 months minimum at IRIS required status before the approval audit takes place. This means there will be a period when TE is manufacturing and supplying from a non-IRIS certified location. The TS certification gives the new location an excellent foundation to reach the IRIS requirements. The parts contained in this PCN are generic catalogue parts. Authorisation from Acc Mgr regarding accepting 90 days as PCN period has been given in e-mail dated Friday 24-6-16.

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	04-NOV-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1102009-2	NO						
1-1102100-7	NO			"114782-000", "HTSS-1-1102100-7"			
1-1102101-7	NO			"HTSS-1-1102101-7", "541148-000"			
1-1102102-7	NO			"086578-000", "HTSS-1-1102102-7"			
1-1102105-2	NO			"941132-000", "HTSS-1-1102105-2"			
1-1102106-2	NO			"215894-000", "HTSS-1-1102106-2"			
1-1102107-2	NO			"CB6678-000", "HTSS-1-1102107-2"			
1-1102109-2	NO			"CE0591-000", "AMPS-1-1102109-2"			

1-1102244-2	NO			"A52823-000", "AMPS-1-1102244-2"			
1-1102246-2	NO			"HTSS-1-1102246-2", "692226-000"			
1-1102271-1	NO			"128588-000", "HTSS-110227111"			
1-1102282-1	NO						
1-1102291-1	NO			"851664-000", "HTSS-110229111"			
1-1102291-8	NO						
1-1102292-6	NO			"CB3208-000", "HTSS-1-1102292-6"			
1-1102296-1	NO			"652750-000", "HTSS-110229611"			
1-1102296-8	NO			"818598-000", "HTSS-110229618"			
1-1102316-6	NO			"CE0675-000", "AMPS-1-1102316-6"			
1-1102331-1	NO			"CE0677-000", "AMPS-1-1102331-1"			
1-1102333-2	NO						
1-1102449-3	NO						
1-1102647-5	NO						
1-1102660-5	NO						
1-1103400-1	NO			"857812-000", "HTSS-110340011"			
1-1103401-1	NO			"993274-000", "HTSS-110340111"			
1-1103402-1	NO			"676316-000", "HTSS-110340211"			
1-1103403-1	NO			"429666-000", "HTSS-110340311"			
1-1103415-1	NO			"CE0607-000", "AMPS-1-1103415-1"			
1-1103417-1	NO			"CE0613-000", "AMPS-1-1103417-1"			
1-1103417-7	NO						
1-1103634-1	NO			"A52670-000", "AMPS-1-1103634-1"			
1-1103635-1	NO			"AMPS-1-1103635-1", "D34822-000"			
1-1103638-1	NO			"AMPS-1-1103638-1", "D77488-000"			
1-1103641-1	NO			"HTSS-1-1103641-1", "676678-000"			
1-1104204-1	NO			"101946-000", "HTSS-110420411"			
1-1105150-1	NO						
1-1106302-9	NO			"670936-000", "HTSS-110630219"			
1-1106305-9	NO			"CE0586-000", "AMPS-1-1106305-9"			
1-1106308-9	NO			"CE0588-000", "AMPS-1-1106308-9"			
1-1106452-0	NO						

1-1106470-9	NO						
1102194-1	NO			"CE0595-000", "AMPS-0-1102194-1"			
1102195-1	NO			"CE0594-000", "AMPS-0-1102195-1"			
1103014-1	NO						
1103015-1	NO						
1103015-2	NO						
1103016-1	NO			"EG7810-000", "AMP-0-1103016-1"			
1103016-2	NO			"EG8010-000", "AMP-0-1103016-2"			
1103019-1	NO			"CS4222-000", "AMP-0-1103019-1"			
1103019-2	NO			"CS4223-000", "AMP-0-1103019-2"			
1103021-1	NO						
1103021-2	NO						
1103022-1	NO						
1103022-2	NO						
1103024-2	NO			"EG8013-000", "AMP-0-1103024-2"			
1104002-1	NO						
1106401-2	NO						
1106403-1	NO						
1106405-1	NO						
1106411-2	NO						
1106425-3	NO						
1106425-4	NO						
1106446-4	NO						
1106452-7	NO						
1107102-1	NO			"256364-000", "HTSS-110710201"			
1108529-1	NO						
1108567-1	NO						
1108616-1	NO						
1108617-1	NO						
1108780-2	NO						
1108782-1	NO			"EG8192-000", "AMP-0-1108782-1"			
1108782-2	NO			"EG8009-000", "AMP-0-1108782-2"			
1108783-1	NO						
1108783-2	NO						
1108784-1	NO			"CS4196-000", "AMP-0-1108784-1"			
1110949-1	NO			"AMP-0-1110949-1", "EH0790-000"			
1110950-2	NO						
1110950-3	NO						
1110952-3	NO						
1110952-7	NO						
1110953-6	NO						
2-1102121-2	NO						
2-1102240-7	NO						

2-1102244-2	NO						
2-1102246-2	NO						
2-1102283-2	NO						
2-1102296-1	NO						
2-1102564-6	NO						
2-1102600-5	NO			"244660-000", "HTSS-110260025"			
2-1102602-5	NO						
2-1102606-5	NO						
2-1102618-5	NO						
2-1102628-5	NO						
2-1102631-5	NO						
2-1102637-5	NO						
2-1102638-5	NO						
2-1102644-5	NO						
2-1102647-5	NO						
2-1102649-5	NO						
2-1102651-5	NO						
2-1102655-5	NO						
2-1102656-5	NO						
2-1102660-5	NO						
2-1102665-5	NO						
2-1103006-3	NO						
2-1103007-3	NO						
2-1103012-3	NO						
2-1103013-3	NO						
2-1103033-3	NO			"303834-000", "AMPS-2-1103033-3"			
2-1103100-3	NO			"943606-000", "HTSS-110310023"			
2-1103101-3	NO			"169724-000", "HTSS-110310123"			
2-1103102-3	NO						
2-1103103-3	NO						
2-1103104-3	NO			"213704-000", "HTSS-110310423"			
2-1103105-3	NO			"869588-000", "HTSS-110310523"			
2-1103112-3	NO						
2-1103113-3	NO			"CE0690-000", "AMPS-2-1103113-3"			
2-1103200-3	NO			"AMPS-2-1103200-3", "F86601-000"			
2-1103202-3	NO			"CA3567-000", "AMPS-2-1103202-3"			
2-1103208-3	NO			"934212-000", "HTSS-110320823"			
2-1103212-3	NO			"CA3568-000", "AMPS-2-1103212-3"			
2-1103618-3	NO						
2-1103626-3	NO						
2-1103634-3	NO			"CE0644-000", "AMPS-2-1103634-3"			
2-1103635-3	NO			"CE0645-000", "AMPS-2-1103635-3"			

2-1103636-3	NO			"074544-000", "HTSS-110363623"			
2-1103637-3	NO			"749886-000", "HTSS-110363723"			
2-1103638-3	NO			"CE0683-000", "AMPS-2-1103638-3"			
2-1103639-3	NO			"D58057-000", "AMPS-2-1103639-3"			
2-1103640-3	NO			"314546-000", "HTSS-11036HEHF"			
2-1103641-3	NO			"279564-000", "HTSS-110364123"			
2-1104000-3	NO						
2-1104002-3	NO						
2-1104008-3	NO						
2-1104010-3	NO						
2-1104012-3	NO						
2-1104013-3	NO						
2-1104014-3	NO			"630688-000", "HTSS-110401423"			
2-1104018-3	NO						
2-1104034-3	NO			"908722-000", "HTSS-110403423"			
2-1104200-3	NO			"336408-000", "HTSS-110420023"			
2-1104202-3	NO			"774704-000", "HTSS-110420223"			
2-1105151-1	NO			"018402-000", "HTSS-110515121"			
2-1105350-1	NO						
3-1105150-1	NO						
3-1105151-1	NO			"125464-000", "HTSS-110515131"			
3-1106214-0	NO						
3-1106302-9	NO						
4-1102700-5	NO			"370096-000", "HTSS-110270045"			
4-1102701-5	NO			"706368-000", "HTSS-110270145"			
4-1102702-5	NO						
4-1105150-1	NO			"254970-000", "HTSS-110515041"			
4-1105151-1	NO			"740856-000", "HTSS-110515141"			
4-1106204-5	NO						
5-1105150-1	NO			"CS4197-000", "AMP-0-5-1105150-1"			
5-1105151-1	NO			"748430-000", "HTSS-110515151"			
5-1106302-9	NO						
6-1105151-1	NO						