


Light is OSRAM

Not For New Design OS-NFND-2021-022

01 September 2021

Expected discontinuation date:	1-5 Years
Reason:	The following products have reached their end of life.
OSRAM OS Expectations:	Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products. Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Not for new design products				Recommended Replacement		
Device	Ordering Code	Brand	Expected PDN start	Device	Datasheet Ordering Code	Brand
SFH 4715S	Q65111A1549	OSLON	12/1/2023	SFH 4715AS	Q65111A6857	OSLON
SFH 4725S	Q65111A2800	OSLON	12/1/2023	SFH 4725AS	Q65112A0782	OSLON
SFH 4725S R33	Q65113A3206	OSLON	12/1/2023	SFH 4725AS R33	Q65113A3208	OSLON
SFH 4715S R33	Q65113A3210	OSLON	12/1/2023	SFH 4715AS R33	Q65113A3215	OSLON