


Not For New Design OS-NFND-2026-001

02 March 2026

Expected discontinuation date:	Q1/2028: KW C2L5L2.TK; KW C3L5L2.TK; KW2 C2LPL3.TK; KW3 C3LPL3.TK; KW2 C2LNL3.TK; KW3 C3LNL3.TK Q4/2029: KW HHL631.TK; KW2 HML631.TK; KW3 HNL631.TK; KW4 HPL631.TK; KW CWLPM3.T1; KW CWLPM3.TK
Reason:	The following products have reached their end of life.
Actions:	Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions. Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products. Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Expected discontinuation date:	Q1/2028: KW C2L5L2.TK; KW C3L5L2.TK; KW2 C2LPL3.TK; KW3 C3LPL3.TK; KW2 C2LNL3.TK; KW3 C3LNL3.TK Q4/2029: KW HHL631.TK; KW2 HML631.TK; KW3 HNL631.TK; KW4 HPL631.TK; KW CWLPM3.T1; KW CWLPM3.TK
Reason:	The following products have reached their end of life.

Not for new design products				Recommended Replacement		
Device	Ordering Code	Brand	Expected PDN start	Device	Datasheet Ordering Code	Brand
KW HHL631.TK	all	OSLON				
KW HHL631.TK-5SS7-4L05L0-2686-1A-R18	Q65115A0688	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-5SSA-4L05M0-2686-A00-S	Q65113A1245	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-5SSB-4L07M0-2686-A00-S	Q65113A4583	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-5SSB-4L07M0-2686-A00-S	Q65113A9718	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SS8-5L06L0-2686-1A-R18	Q65113A9369	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SS8-6L07M0-2686-1A-R18	Q65115A0689	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SS9-5L05M0-2686-1A-S	Q65113A6899	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SS9-5L06L0-2686-1A-R18	Q65113A9554	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SS9-5L06L0-2686-1A-S	Q65113A7581	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SSA-5L06L0-2686-1A-R18	Q65113A5589	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SSA-5L06L0-2686-1A-S	Q65113A8787	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SSA-5L06M0-2686-1A-S	Q65113A5233	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SSA-6L07M0-2686-1A-R18	Q65113A4824	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SSB-5L06M0-2686-1A-R18	Q65115A3102	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-6SSB-6L07M0-2686-A00-S	Q65113A1244	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON
KW HHL631.TK-S7SB-6L07M0-2686-1A-R18	Q65113A8865	OSLON	31-12-29	KW HHL533.TK-S6S9-5L26M1-48A4-1A-S	Q65115A0675	OSLON

Expected discontinuation date:	Q1/2028: KW C2L5L2.TK; KW C3L5L2.TK; KW2 C2LPL3.TK; KW3 C3LPL3.TK; KW2 C2LNL3.TK; KW3 C3LNL3.TK Q4/2029: KW HHL631.TK; KW2 HML631.TK; KW3 HNL631.TK; KW4 HPL631.TK; KW CWLPM3.T1; KW CWLPM3.TK						
Reason:	The following products have reached their end of life.						
KW2 HML631.TK	all	OSLON					
KW2 HML631.TK-6DT0-5L06L0-SC6B-1A-S	Q65113A6906	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-6DT1-4L05M0-SC6B-A00-S	Q65113A1243	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-6DT1-5L0-SC6B-A00-S	Q65113A8323	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-6DT2-4L05L0-SC6B-1A-R18	Q65113A8690	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-6DT2-4L07M0-SC6B-A00-S	Q65113A4584	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DD8-5L06L0-SC6B-1A-R18	Q65115A2935	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DD9-5L05M0-SC6B-1A-S	Q65115A0803	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DD9-5L05M0-SC6B-1A-S	Q65113A9129	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DD9-5L06L0-SC6B-1A-R18	Q65113A6212	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DD9-5L06L0-SC6B-1A-R18	Q65115A2031	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DD9-6L07M0-SC6B-1A-R18	Q65115A1816	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DT0-5L06L0-SC6B-1A-R18	Q65113A8819	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DT0-5L06L0-SC6B-1A-S	Q65115A1043	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DT0-5L06L0-SC6B-1A-S	Q65115A2341	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DT1-5L0-SC6B-1A-R18	Q65113A8565	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DT1-6L07M0-SC6B-1A-R18	Q65113A8630	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DT1-6L07M0-SC6B-1A-S	Q65113A8432	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-7DT2-6L07M0-SC6B-A00-S	Q65113A1298	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	
KW2 HML631.TK-D8T2-6L07M0-SC6B-1A-S	Q65115A1793	OSLON	31-12-29	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON	

Expected discontinuation date:	Q1/2028: KW C2L5L2.TK; KW C3L5L2.TK; KW2 C2LPL3.TK; KW3 C3LPL3.TK; KW2 C2LNL3.TK; KW3 C3LNL3.TK Q4/2029: KW HHL631.TK; KW2 HML631.TK; KW3 HNL631.TK; KW4 HPL631.TK; KW CWLPM3.T1; KW CWLPM3.TK					
Reason:	The following products have reached their end of life.					
KW3 HNL631.TK	all	OSLON				
KW3 HNL631.TK-6TT9-4L05L0-JCAB-1A-S	Q65113A5396	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-6TTA-5L06L0-JCAB-1A-S	Q65113A4861	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-6TTB-4L05M0-JCAB-A00-S	Q65113A1249	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-6TTC-4L07M0-JCAB-A00-S	Q65113A4585	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-7TT9-5L2-JCAB-1A-S	Q65113A7065	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-7TTA-5L06L0-JCAB-1A-S	Q65113A9663	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-7TTC-6L07M0-JCAB-A00-S	Q65113A1297	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-T8TA-5L06L0-JCAB-1A-R18	Q65115A1708	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-T8TA-6L07M0-JCAB-1A-S	Q65113A8463	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-T8TB-6L07L0-JCWC-1A-R18	Q65115A1086	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 HNL631.TK-T8TC-6L07M0-JCAB-1A-R18	Q65113A6907	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW4 HPL631.TK	all	OSLON				
KW4 HPL631.TK-BCBH-4L05M0-AGAE-A00-S	Q65113A1248	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW4 HPL631.TK-BCBJ-4L07M0-AGAE-A00-S	Q65113A4586	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW4 HPL631.TK-BDBH-5L06M0-AGAE-1A-S	Q65113A7906	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW4 HPL631.TK-BDBJ-6L07M0-AGAE-A00-S	Q65113A1296	OSLON	31-12-29	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW CWLPM3.T1	all	OSLON				
KW CWLPM3.T1-S4S8-4L14L2-0-A00-S	Q65113A6598	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW CWLPM3.T1-S5S7-4L2-0-1A-R18	Q65115A1673	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON

Expected discontinuation date:	Q1/2028: KW C2L5L2.TK; KW C3L5L2.TK; KW2 C2LPL3.TK; KW3 C3LPL3.TK; KW2 C2LNL3.TK; KW3 C3LNL3.TK Q4/2029: KW HHL631.TK; KW2 HML631.TK; KW3 HNL631.TK; KW4 HPL631.TK; KW CWLPM3.T1; KW CWLPM3.TK					
Reason:	The following products have reached their end of life.					
KW CWLPM3.TK	all	OSLON				
KW CWLPM3.TK-5SS9-4L07M0-2686-A00-S	Q65113A3327	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW CWLPM3.TK-X5X8-5L07M0-W365-350-S	Q65113A3328	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW CWLPM3.TK-5SS8-5L06L0-2686-1A-R18	Q65113A5545	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW CWLPM3.TK-6SS9-6L07M0-2686-A00-S	Q65113A6718	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW CWLPM3.TK-6SS9-5L06L0-2686-1A-R18	Q65113A8281	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW CWLPM3.TK-6SS8-5L06L0-2686-1A-R18	Q65113A9640	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW CWLPM3.TK-5SS9-6L07M0-2686-1A-R18	Q65115A0025	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW CWLPM3.TK-6SS9-5L07M0-2686-350-S	Q65115A1269	OSLON	01-01-28	KW CELNM4.TK-S7SA-5L26M1-2686-1A-S	Q65115A1341	OSLON
KW C2L5L2.TK	all	OSLON				
KW C2L5L2.TK-D3D9-4L07M0-0-A00-S	Q65113A0756	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D3D7-5L06L0-0-1A-R18	Q65113A2907	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D4D8-5L06L0-0-1A-R18	Q65113A3278	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D4D6-5L06L0-0-1A-R18	Q65113A3650	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D5D7-6L07L0-0-1A-R18	Q65113A3715	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D3D5-4L05L0-0-1A-R18	Q65113A4101	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D4D6-5L05M0-0-1A-S	Q65113A4116	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D5D7-5L06L0-0-1A-R18	Q65113A4200	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D4D6-6L07L0-0-1A-R18	Q65113A4511	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D4D5-5L06L0-0-1A-R18	Q65113A5227	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW C2L5L2.TK-D4D7-5L06L0-0-1A-R18	Q65113A7777	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON

Expected discontinuation date:	Q1/2028: KW C2L5L2.TK; KW C3L5L2.TK; KW2 C2LPL3.TK; KW3 C3LPL3.TK; KW2 C2LNL3.TK; KW3 C3LNL3.TK Q4/2029: KW HHL631.TK; KW2 HML631.TK; KW3 HNL631.TK; KW4 HPL631.TK; KW CWLPM3.T1; KW CWLPM3.TK					
Reason:	The following products have reached their end of life.					
KW C3L5L2.TK	all	OSLON				
KW C3L5L2.TK-T3T9-4L07M0-0-A00-S	Q65113A0769	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW C3L5L2.TK-T3T7-5L06L0-0-1A-R18	Q65113A2906	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW C3L5L2.TK-T4T6-5L06L0-0-1A-R18	Q65113A3649	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW C3L5L2.TK-T5T7-6L07L0-0-1A-R18	Q65113A3714	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW C3L5L2.TK-T5T7-5L06L0-0-1A-R18	Q65113A4199	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW C3L5L2.TK-T4T6-6L07L0-0-1A-R18	Q65113A4512	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW C3L5L2.TK-T4T6-5L05M0-0-1A-R18	Q65113A4880	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW C3L5L2.TK-T4T7-5L06L0-0-1A-R18	Q65113A7776	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW2 C2LPL3.TK	all	OSLON				
KW2 C2LPL3.TK-6DT2-5L35M3-0-1A-S	Q65113A5653	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LPL3.TK-6DT2-5L16M1-0-1A-S	Q65113A5654	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LPL3.TK-6DT2-5L25M2-0-1A-S	Q65113A5658	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LPL3.TK-7DT0-5L25M2-2F-1A-S	Q65115A1053	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LPL3.TK-7DT0-5L35M3-2F-1A-S	Q65115A1779	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LPL3.TK-7DD9-6L16M1-0-1A-R18	Q65115A2527	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON

Expected discontinuation date:	Q1/2028: KW C2L5L2.TK; KW C3L5L2.TK; KW2 C2LPL3.TK; KW3 C3LPL3.TK; KW2 C2LNL3.TK; KW3 C3LNL3.TK Q4/2029: KW HHL631.TK; KW2 HML631.TK; KW3 HNL631.TK; KW4 HPL631.TK; KW CWLPM3.T1; KW CWLPM3.TK					
Reason:	The following products have reached their end of life.					
KW3 C3LPL3.TK	all	OSLON				
KW3 C3LPL3.TK-6TTC-5L35M3-0-1A-S	Q65113A5647	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-6TTC-5L25M2-0-1A-S	Q65113A5648	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-6TTC-5L16M1-0-1A-S	Q65113A5649	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-6TTC-5L16M1-0-1A-S	Q65113A8828	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-89TC-6L1-0-1A-R18	Q65113A9242	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-6TT9-5L35M3-WP-1A-S	Q65115A1057	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-6TT9-5L25M2-WP-1A-S	Q65115A1058	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-T8TC-5L2-0-1A-R18	Q65115A2017	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-6TT8-6L16M1-0-1A-R18	Q65115A2528	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LPL3.TK-89TA-6L16M1-0-1A-R18	Q65115A2552	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW2 C2LNL3.TK	all	OSLON				
KW2 C2LNL3.TK-D5T1-5L35M3-0-1A-S	Q65113A5655	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LNL3.TK-D5T1-5L16M1-0-1A-S	Q65113A5656	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LNL3.TK-D5T1-5L25M2-0-1A-S	Q65113A5659	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LNL3.TK-D6T0-6L1-0-1A-R18	Q65113A8773	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LNL3.TK-D6D8-5L3-0-1A-R18	Q65113A8849	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LNL3.TK-D6D8-5L2-0-1A-R18	Q65113A9481	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LNL3.TK-D6T0-5L2-0-1A-R18	Q65115A2016	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON
KW2 C2LNL3.TK-D6T0-6L16M1-0-1A-R18	Q65115A3311	OSLON	01-01-28	KW2 HIL533.TK-D7T1-5L26M1-S8A7-1A-S	Q65115A0679	OSLON

Expected discontinuation date:	Q1/2028: KW C2L5L2.TK; KW C3L5L2.TK; KW2 C2LPL3.TK; KW3 C3LPL3.TK; KW2 C2LNL3.TK; KW3 C3LNL3.TK Q4/2029: KW HHL631.TK; KW2 HML631.TK; KW3 HNL631.TK; KW4 HPL631.TK; KW CWLPM3.T1; KW CWLPM3.TK					
Reason:	The following products have reached their end of life.					
KW3 C3LNL3.TK	all	OSLON				
KW3 C3LNL3.TK-T5TB-5L35M3-0-1A-S	Q65113A5650	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T5TB-5L25M2-0-1A-S	Q65113A5651	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T5TB-5L16M1-0-1A-S	Q65113A5652	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T6T8-5L3-0-1A-R18	Q65113A7865	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T6T8-5L2-0-1A-R18	Q65113A8337	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T6TA-6L1-0-1A-R18	Q65113A8850	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T6T8-5L2-0-1A-R18	Q65113A9480	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T6T8-5L1-0-1A-R18	Q65115A1780	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T6TA-5L2-0-1A-R18	Q65115A2018	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON
KW3 C3LNL3.TK-T6TA-6L16M1-0-1A-R18	Q65115A3312	OSLON	01-01-28	KW3 HJL533.TK-7TTB-5L26M1-JCAB-1A-S	Q65115A0682	OSLON