





Title of Change:	SUPPLY RESILIENCY: Qualification of onsemi Cebu, Philippines as an additional turnkey site for PQFN56W devices	
Effective date:	27 Jan 2026	
Contact information:	Contact your local onsemi Sales Office	
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.	
Change Category:	Assembly Change	
Change Sub-Category(s):	Manufacturing Site Addition	
Sites Affected:		
onsemi Sites		External Foundry/Subcon Sites
onsemi Cebu, Philippines		None
Description and Purpose:		
<p>This Product Bulletin is issued to notify customers of the addition of a new manufacturing site as part of onsemi’s Supply Resiliency initiatives.</p> <p>To strengthen supply chain resilience and enhance operational flexibility, onsemi is introducing the PQFN56 wired package with an alternative assembly and test location. The original part numbers will remain unchanged and active, while the new part numbers will retain the same specifications and performance, with updates limited only to site-specific attributes.</p> <p>Electrical performance and device characteristics remain unaffected, and both qualified sites will be used to support customer demand.</p> <p>This initiative enables dual sourcing for strategic packages that are currently sole-sourced, improving capability, increasing supply chain flexibility, and reducing overall risk.</p> <p>If you are interested in receiving material sourced from an alternative site, please contact your local sales representative.</p>		
	Original Part Numbers	Additional New Part Numbers
Assembly and Test Site	GEM, China	onsemi Cebu, Philippines
Product Marking Change	GEM marking 	Cebu marking 
	NTMFS006N08MC 	NTMFS006N08MC-NC 
Part number Change	FDMS86163P FDMS86182 NTMFS006N08MC	FDMS86163P-NC FDMS86182-NC NTMFS006N08MC-NC



Electrical Characteristic Summary:

Electrical characteristics are not impacted.

List of Affected Standard Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

NTMFS006N08MC

FDMS86182

FDMS86163P