

Title of Change:	FDN304P Missing P Character in Product Laser Marking.
Effective date:	19 Sep 2022
Contact information:	Contact your local onsemi Sales Office or KrisJudelo.Dayna@onsemi.com
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.
Change Category:	Others
Change Sub-Category(s):	Shipping/Packaging/Marking

Sites Affected:

onsemi Sites	External Foundry/Subcon Sites
onsemi Cebu, Philippines	None
onsemi Seremban, Malaysia	

Description and Purpose:


This is to inform that we have a cosmetic (marking) issue on the product FDN304P.

FDN304P has 2 assembly sites, onsemi Malaysia and onsemi Cebu, Philippines both sites had same marking error – missing the “P” character.

The goods are 100% tested to production test program and no issue on electrical performance.

We have taken corrective action to correct the error at our Malaysia and Philippines production sites last May 11,2022.

See below for illustration for reference.



Below are the affected lots.

PR000002T0	PR000002TJ	PR000002U2	PN16REW03R
PR000002T1	PR000002TK	PR000002U3	PN16REW03S
PR000002T2	PR000002TL	PR000002U4	PN16REW03T
PR000002T3	PR000002TM	PR000002U5	PN16REW03V
PR000002T4	PR000002TN	PR000002U6	PN16REW03W
PR000002T5	PR000002TO	PR000002U7	PN16REW040
PR000002T6	PR000002TP	PR000002U8	PN16REW042
PR000002T7	PR000002TQ	PR000002U9	PN16REW043
PR000002T8	PR000002TR	PR000002UA	PN17REW02V
PR000002T9	PR000002TS	PR000002UB	PN17REW02Y
PR000002TA	PR000002TT	PR000002UC	PN17REW030
PR000002TB	PR000002TU	PR000002UD	PN17REW031
PR000002TC	PR000002TV	PR000002UE	PN17REW035
PR000002TD	PR000002TW	PR000002UF	PN17REW037
PR000002TE	PR000002TX	PR000002T0	PN17REW038
PR000002TF	PR000002TY	PN12REW02A	PN17REW03A
PR000002TG	PR000002TZ	PN12REW02G	PN17REW03C
PR000002TH	PR000002U0	PN12REW02Z	MY16REW28A
PR000002TI	PR000002U1	PN16REWA3P	PN16REW03P

List of Affected Standard Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [**PCN Customized Portal**](#).

FDN304P		
---------	--	--