



## Product Change Notification / SYST-02LCYE601

---

### Date:

03-Aug-2021

### Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

### PCN Type:

Silicon Die Revision

### Notification Subject:

ERRATA - dsPIC33CH512MP508 Family Silicon Errata and Data Sheet Clarification Revision

### Affected CPNs:

[SYST-02LCYE601\\_Affected\\_CPN\\_08032021.pdf](#)

[SYST-02LCYE601\\_Affected\\_CPN\\_08032021.csv](#)

### Notification Text:

SYST-02LCYE601

Microchip has released a new Product Documents for the dsPIC33CH512MP508 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [dsPIC33CH512MP508 Family Silicon Errata and Data Sheet Clarification](#).

**Notification Status:** Final

**Description of Change:** Adds silicon revision A2

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Estimated First Ship Date:** 01 Sept 2021

NOTE: Please be advised that after the estimated first ship date customers may receive pre and post change parts.

**Markings to Distinguish Revised from Unrevised Devices:** Traceability Code

## **Attachments:**

[dsPIC33CH512MP508 Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.