



Product Change Notification / SYST-21NWMU176

Date:

22-Apr-2021

Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

PCN Type:

Document Change

Notification Subject:

ERRATA - dsPIC33CH512MP508 Family Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-21NWMU176_Affected_CPN_04222021.pdf](#)
[SYST-21NWMU176_Affected_CPN_04222021.csv](#)

Notification Text:

SYST-21NWMU176

Microchip has released a new Product Documents for the dsPIC33CH512MP508 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [dsPIC33CH512MP508 Family Silicon Errata and Data Sheet Clarification](#).

Description of Change:

1. Update's silicon issue 26 (Secondary CPU).
2. Adds silicon issue 27 (SCCP).
3. Adds data sheet clarification 17 (Electrical Characteristics).

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 22 Apr 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[dsPIC33CH512MP508 Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.