



Product Change Notification / SYST-31HPWF472

Date:

01-Sep-2021

Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

PCN Type:

Document Change

Notification Subject:

ERRATA - dsPIC33CH128MP508 Family Silicon Errata and Datasheet Clarification

Affected CPNs:

[SYST-31HPWF472_Affected_CPN_09012021.pdf](#)
[SYST-31HPWF472_Affected_CPN_09012021.csv](#)

Notification Text:

SYST-31HPWF472

Microchip has released a new Product Documents for the dsPIC33CH128MP508 Family Silicon Errata and Datasheet Clarification of devices. If you are using one of these devices please read the document located at [dsPIC33CH128MP508 Family Silicon Errata and Datasheet Clarification](#).

Notification Status: Final

Description of Change:

1. Updates silicon issue 36 (Secondary CPU).
2. Adds silicon issues 38 (ADC) and 39 (POR).

Impacts to Data Sheet: See above details

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 1 September 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[dsPIC33CH128MP508 Family Silicon Errata and Datasheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.