

Product Change Notification - SYST-21HHID043

Date:

22 Apr 2020

Product Category:

32-bit Microcontrollers

Affected CPNs:**Notification subject:**

ERRATA - PIC32MX575/675/695/775/795 Family Errata and Datasheet Clarification

Notification text:

SYST-21HHID043

Microchip has released a new Product Documents for the PIC32MX575/675/695/775/795 Family Errata and Datasheet Clarification of devices. If you are using one of these devices please read the document located at [PIC32MX575/675/695/775/795 Family Errata and Datasheet Clarification](#).

Notification Status: Final

Description of Change: 1) Added silicon issue 52. Module: "USB Low-Speed Mode";
2) Removed obsolete Data Sheet Clarifications for Feature List.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 22 Apr 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[PIC32MX575/675/695/775/795 Family Errata and Datasheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.