



## Product Change Notification / SYST-05IOYF175

---

**Date:**

21-Sep-2022

**Product Category:**

32-bit Microcontrollers

**PCN Type:**

Document Change

**Notification Subject:**

ERRATA - SAM D10 Family Silicon Errata and Data Sheet Clarification

**Affected CPNs:**

[SYST-05IOYF175\\_Affected\\_CPN\\_09212022.pdf](#)  
[SYST-05IOYF175\\_Affected\\_CPN\\_09212022.csv](#)

**Notification Text:**

SYST-05IOYF175

Microchip has released a new Errata for the SAM D10 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [SAM D10 Family Silicon Errata and Data Sheet Clarification](#).

**Notification Status:** Final

**Description of Change:** Revision C Document (09/2022) This revision includes numerous typographical updates, along with the following new information: The following errata were added: • 4. Module: "PORT I/O Pin Controller" • 5. Module: "BOD33 Hysteresis"

**Impacts to Data Sheet:** None

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 21 Sep 2022

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## **Attachments:**

**SAM D10 Family Silicon Errata and Data Sheet Clarification**

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.