








SYMBOL DEFINITION			MISSING SYMBOLS	
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL □ DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.			TOTAL NO OF INSPECTIONS REQUIRED	28
			LAST NO. USED	19

DWG STATUS				ZONE		REVISION HISTORY		AUTH	DR	APVD
DATE	STG	REV	N/P	CHG						
03AP07	R	01	-	-		CREATED PD		400744	AZ	OY
26JN07	R	02	-	-		FLATTENED THE SLANT FACE OF THE LOCK ARM		401772	AZ	OY
13DE07	R	03	-	-		LIFTED THE SIDE WALLS OF THE LOCK ARM 0.675.		403271	AZ	OY
27FE08	R	03	AA	-		RELAXED TOLERANCE		403958	AZ	OY
14MY08	R	03	AB	-		DIM#7 WAS 12.85 +/-0.05 DIM#17 WAS 33.5 +/-0.1		404696	SBH	JWG
23MY08	R	03	AC			DIM #7 WAS 12.8+0.2/-0.1		404824	SBH	JWG
26MY08	R	03	AD			DIM#7 WAS 12.85+0.2/-0.1		404837	SBH	JWG



NOTES

- UNLESS OTHERWISE SPECIFIED AND/OR INDICATED:
DIMENSIONS ARE TO FACE OF VIEW SHOWN AND AUTOMATICALLY ROUNDED BY COMPUTER FOR INSPECTION (SEE MATH MODEL FOR PRECISE DIMENSIONS). FOR ALL OTHER DIMENSIONS NOT SHOWN BUT REQUIRED FOR TOOL BUILD, SEE MATH MODEL FOR PRECISE TOOL PATH DATA.
- THIS PRODUCT IS NOT CATEGORIZED AS AN APPEARANCE ITEM. MINOR IMPERFECTIONS INCLUDING, BUT NOT LIMITED TO, FLOW MARKS, COLOR BLEMISHES, GATE VESTIGE, AND SOFT FLASH THAT DO NOT AFFECT THE FIT, FORM, OR FUNCTION OF THE PART ARE PERMISSIBLE PER NAP 4.10-18.
- FOR APPLICATION DATA SEE THE APPLICATION DRAWING.

17		PROCESS SENSITIVE DIMENSION	
		DIMENSIONS ENCLOSED IN () INDICATE REFERENCE DIMENSIONS AND NO TOLERANCE LIMITS ARE ESTABLISHED	

DIMENSIONAL RANGE (MM)						CHART		P
FROM	> 0	> 30	> 70	> 100	> 150	> 200	> 250	> 300
TO	30	70	100	150	200	250	300	400
TOLERANCE UNLESS OTHERWISE SPECIFIED								
	±0.1	±0.3	±0.4	±0.5	±0.6	±0.8	±1	±1.2
ANGULAR TOLERANCE ±1°								
E 1 1								