

①

G

①

1

A LINE DRAWN THROUGH A PART NUMBER INDICATES THAT PHYSICAL PARTS ARE NOT AVAILABLE FOR ORDERING.

PART NUMBERS THAT DO NOT HAVE A LINE PRESENT INDICATE THAT PHYSICAL PARTS ARE AVAILABLE FOR ORDERING.

CONTACT ACTIV SALES TO ASSURE AVAILABILITY OF PARTS.

The diagram shows a cross-section of a part with a sharp corner. A horizontal line is drawn through the part number area, indicating that physical parts are not available for ordering. The corner is labeled with a radius of R 0.1 MAX. A vertical line is drawn through the part number area, indicating that physical parts are available for ordering. The corner is labeled with a radius of R 0.2 MAX.

SHARP CORNER TOLERANCE

B

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[Aptiv:](#)
[33308963](#)