

SYMBOL DEFINITION				MISSING SYMBOLS												
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.		TOTAL NO OF INSPECTIONS REQUIRED	9	NO MISSING SYMBOL NUMBER	DWG STATUS					ZONE	REVISION HISTORY		AUTH	DR	APD	
					DATE	STG	REV	N/P	CHG						1	2
					30JL08	R	H3	-	-		DRAWN TO PD AND UPDATED MAT'L CALLOUT		405598	DWC	SCR	AEC
					DBAP09	R	H4	-	-		DIMW 41.92 ±0.15/-0.5 WAS 41.92 ±0.15, 42.16 ±0.15/-0.54 WAS 42.16 ±0.15 & 8.8 ±0.3/-0.15 WAS 8.8 ±0.2/-0.15		407801	LMC	ECB	JPM
		LAST NO. USED	8													

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[Aptiv:](#)
[12020840](#)