



△ Precoutions

◆Notification for Insertion Extraction

1) Please insert(extract) the crimping socket straight to the mating connector.
Insertion(extraction) at tilted angles applies load concentration to the connetor end and may cause deformation (at connection area, socket and header case, etc). There is firing risk using this kind of defomed connector.







2) When it is hard to extract, please lightly insert the connector beforehand and then pull it with releasing the lock. Forced extraction has a risk of connector breakage.


◆Notification of wiring


Ţ.

1) When using a thick cable, short cable length and bending close to the connector end, these load concentration may couse deformation.

Please note that there is firing risk using deformed connector.

When installing, please refrain from stress concentration such as cable bending close to the connector end or cable twisting.





ompleted.

PART DF22-2P-7. 92DS(35)

CODE CL680-1008-5-35

2) When applying load to connector end, please use the retainer for reducing the stress affection on the connector.

Retainer shall be installed after inserted crimping contact completely. It might be impossible to insert it when terminal installation is incompleted.

FORM HC0011-5-8 1

-

5

## **Mouser Electronics**

**Authorized Distributor** 

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Hirose Electric: DF22-2P-7.92DS(35)