






Jan.1.2022 Copyright 2022 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



Recommended PC board hole pattern (mounting side)



Notes 1 The dimensions in parentheses are for reference.

3	PHOSPHOR BRONZE	Contact area : Gold 0.2μm min.	5	PHOSPHOR BRONZE	Contact area : Gold 0.2μm min.		
		Dip area : TIN-Plating 2μm min.			Dip area : TIN-Plating 2μm min.		
		Under plating : Nickel 2.5μm min.			Under plating : Nickel 2.5μm min.		
2	PHOSPHOR BRONZE	Contact area : Gold 0.2μm min.	4	PHOSPHOR BRONZE	Contact area : Gold 0.2μm min.		
		Dip area : TIN-Plating 2μm min.			Dip area : TIN-Plating 2μm min.		
		Under plating : Nickel 2.5μm min.			Under plating : Nickel 2.5μm min.		
1	PBT	BLACK UL94V-0					
NO. MATERIAL		FINISH , REMARKS		NO. MATERIAL		FINISH , REMARKS	

UNITS mm		SCALE	COUNT	DESCRIPTION OF REVISIONS	DESIGNED	CHECKED	DATE
		2 : 1					
 HIROSE ELECTRIC CO., LTD.		APPROVED	: HT. YAMAGUCHI	18.06.25	DRAWING NO. EDC-019015-71-21		
		CHECKED	: HT. YAMAGUCHI	18.06.25	PART NO. HIF6A-26DA-1.27DS(71)		
		DESIGNED	: TY. EDAGAWA	18.06.25	CODE NO. CL631-0002-3-71		
		DRAWN	: MK. OKI	18.06.21	 1/1		

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[Hirose Electric:](#)

[HIF6A-26DA-1.27DS\(71\)](#)