XY2SB99

replacement seal - for two-hand control station

Product availability: Non-Stock - Not normally stocked in distribution facility



Main	
Range of product	Preventa XY2
Accessory / separate part designation	Replacement seal
Accessory / separate part type	Seal
Accessory / separate part category	Replacement parts
Accessory / separate part destination	Two-hand ergonomic control station

Complementary

Product weight	0.66 lb(US) (0.3 kg)
----------------	----------------------

Ordering and shipping details

Category	22411 - LIMIT SWITCHES,IEC,XCKJ	
Discount Schedule	Т	
GTIN	003389110151756	
Nbr. of units in pkg.	1	
Package weight(Lbs)	0.7000000000000007	
Returnability	N	
Country of origin	FR	

Offer Sustainability

California proposition 65	WARNING: This product can expose you to chemicals including:
Substance 1	Nickel compounds, which is known to the State of California to cause cancer, and
Substance 2	Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm.
More information	For more information go to www.p65warnings.ca.gov

Contractual warranty

Warranty period	18 months

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Schneider Electric: XY2SB99