


Product availability: Stock - Normally stocked in distribution facility



### Main

|                                       |                                 |
|---------------------------------------|---------------------------------|
| Range of product                      | Preventa Safety detection       |
| Accessory / separate part category    | Mounting and fixing accessories |
| Accessory / separate part type        | Actuator                        |
| Accessory / separate part designation | Pivoting actuator               |
| Accessory / separate part destination | Metal guard switch              |


### Complementary

|                       |   |
|-----------------------|---|
| Product compatibility | XCS<br>XCSA<br>XCSE<br>XCSLE<br>XCSLF<br>XCSB |
| Product weight        | 0.21 lb(US) (0.095 kg)                        |

### Ordering and shipping details

|                       |                                 |
|-----------------------|---------------------------------|
| Category              | 22411 - LIMIT SWITCHES,IEC,XCKJ |
| Discount Schedule     | T                               |
| GTIN                  | 00785901348993                  |
| Nbr. of units in pkg. | 1                               |
| Package weight(Lbs)   | 0.23000000000000001             |
| Returnability         | Y                               |
| Country of origin     | FR                              |

### Offer Sustainability

|                                  |  |
|----------------------------------|--|
| RoHS (date code: YYWW)           | Compliant - since 0948 - Schneider Electric declaration of conformity  Schneider Electric declaration of conformity |
| REACH                            | Reference not containing SVHC above the threshold  |
| Product end of life instructions | Available  |
| California proposition 65        | WARNING: This product can expose you to chemicals including:   |
| - - - - - Substance 1            | Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and  |
| - - - - - Substance 2            | Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm.   |
| - - - - - More information       | For more information go to <a href="http://www.p65warnings.ca.gov">www.p65warnings.ca.gov</a>  |

### Contractual warranty

|                 |           |
|-----------------|-----------|
| Warranty period | 18 months |
|-----------------|-----------|

# Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

[Schneider Electric:](#)

[XCSZ03](#)