




Bussmann

Semiconductor Fuse

70-1000A, 150 Volts

BIF Document
35785310

Size



Minimum Melting

Time-Current Characteristic Curves

FWA 70A-1000A

Approved: **NN**

Page **1 of 3**

Rev. Date: **SEPT-97**

Pub. Date: **JAN-98**

COOPER Bussmann
7-11-01 SB01191

BUSSMANN
P.O. Box 14460
St. Louis, MO 63178-4460
U.S.A.
Phone: 314-394-2877
Fax: 800-544-2570
Int'l Fax: 314-527-1413

BUSSMANN U.K.
Burton-on-the-Wolds
Leicestershire LE12 5TH
England
Phone: 44-1509-882737
Fax: 44-1509-882786

BUSSMANN DENMARK
5 Literbuen
DK-2740 Skovlunde
Copenhagen, Denmark
Phone: 45-4485-0900
Fax: 45-4485-0901

Bussmann reserves the right without notice to change design and/or discontinue distribution of this product.




Bussmann

Semiconductor Fuse

70-400A, 150 Volts

BIF Document
35785310

Size



Peak Let-Through

Time-Current Characteristic Curves

FWA 70A-400A

Approved: **NN**

Page **2 of 3**

Rev. Date: **SEPT-97**

Pub. Date: **JAN-98**




Semiconductor Fuse

500-1000A, 150 Volts

BIF Document
35785310

Size



Peak Let-Through

Cut-Off Current Characteristic Curves

FWA 500A-1000A

Approved: **NN**

Rev. Date: **SEPT-97**

Page **3 of 3**

Pub. Date: **JAN-98**

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Eaton:

[FWA-100B-10](#) [FWA-150B-10](#) [FWA-200B-10](#) [FWA-250B-10](#) [FWA-300B-10](#) [FWA-350B-10](#) [FWA-400B-10](#) [FWA-150ASI4](#) [FWA-70BASI1](#) [FWA-100B\(10\)](#) [FWA-150B\(10\)](#) [FWA-200B\(10\)](#) [FWA-250B\(10\)](#) [FWA-300B\(10\)](#) [FWA-350B\(10\)](#) [FWA-400B\(10\)](#)