

Wear part, fan for variable speed drive, Altivar Process 600 900, IP55, from 30 to 90kW, from 380 to 480V

VX5VP50BC001

Main

Range compatibility	Altivar Process 600/900	
Accessory / separate part type	Internal fan	
Accessory / separate part category	Cooling accessory	
Product or component type	Fan	

Complementary

Kit composition	Fan Mounting bracket Instruction sheet	
Product compatibility	Variable speed drive ATV650 wall mount 30 kW 380480 V	
	Variable speed drive ATV650 wall mount 37 kW 380480 V	
	Variable speed drive ATV650 wall mount 45 kW 380480 V	
	Variable speed drive ATV650 wall mount 55 kW 380480 V	
	Variable speed drive ATV650 wall mount 75 kW 380480 V	
	Variable speed drive ATV650 wall mount 90 kW 380480 V	
	Variable speed drive ATV950 wall mount 30 kW 380480 V	
	Variable speed drive ATV950 wall mount 37 kW 380480 V	
	Variable speed drive ATV950 wall mount 45 kW 380480 V	
	Variable speed drive ATV950 wall mount 55 kW 380480 V	
	Variable speed drive ATV950 wall mount 75 kW 380480 V	
	Variable speed drive ATV950 wall mount 90 kW 380480 V	

Packing Units

Unit Type of Package 1	PCE
Number of Units in Package 1	1
Package 1 Height	7.500 cm
Package 1 Width	17.000 cm
Package 1 Length	23.000 cm
Package 1 Weight	232.000 g
Unit Type of Package 2	S04
Number of Units in Package 2	8
Package 2 Height	30.000 cm
Package 2 Width	40.000 cm
Package 2 Length	60.000 cm
Package 2 Weight	2.560 kg

Contractual warranty

Warranty 18 months



Schneider Electric aims to achieve Net Zero status by 2050 through supply chain partnerships, lower impact materials, and circularity via our ongoing "Use Better, Use Longer, Use Again" campaign to extend product lifetimes and recyclability.

Environmental Data explained >

How we assess product sustainability >

Use Better

EU RoHS Directive	Pro-active compliance (Product out of EU RoHS legal scope)
California proposition 65	WARNING: This product can expose you to chemicals including: Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov