

TO

Technical drawing of a mechanical part, likely a connector or fastener, showing multiple views and dimensions.

Views:

- Top View:** Shows the overall shape with a central slot and a cross-hatched section. A dimension line indicates a length of 15.7 (in parentheses).
- Front View:** Shows the profile of the part with a central slot and a cross-hatched section. Dimensions include 7.2 ± 0.5 , 2.5 ± 0.3 , and 6 ± 0.5 .
- Side View:** Shows the side profile of the part with a central slot and a cross-hatched section.
- Bottom View:** Shows the bottom profile of the part with a central slot and a cross-hatched section.
- End View:** Shows the end profile of the part with a central slot and a cross-hatched section.

Dimensions:

- Overall length: 15.7 (in parentheses)
- Segment 1: 7.2 ± 0.5
- Segment 2: 2.5 ± 0.3
- Segment 3: 6 ± 0.5
- End view diameter: $\phi 5 \pm 0.3$

Notes:

- A circled number "1" is present near the top view.
- A diagonal line with a triangle symbol is used to indicate a cross-section.