# 80,000 Count Digital Multimeter

- 80,000 count Dual Display
- Basic DC accuracy is 0.05%
- Pulse output with frequency selection from 0.5Hz to 5KHz with duty cycles from 1% to 99%
- Measures frequency, ms Pulse width and duty cycle
- AC and AC+DC TRUE RMS measurements.
- Hi and Lo limit testing
- dBm measurement using 20 reference Impedances
- Min/Max/AVG
- Peak hold and Relative mode
- RS232 port
- CE and Category II 1000V and Cat III 600V safety standards
- Built in 10 hour timer



6800

# SPECIFICATIONS =

# nV DC

Ranges: 80 mV, 800 mV; Best Resolution:  $1\mu V$  Accuracy:  $\pm 0.05\%$  + 10d; Input Impedance:  $1G\Omega$ 

# DC Volts

Ranges: 8V, 80 V, 800V, 1000V; Best Resolution: 100 $\mu$ V Accuracy:  $\pm$ (0.05% + 10d); Max. Input Voltage: 1000V DC Input Impedance: 10M $\Omega$ 

# AC mV/Volts TRUE RMS

Ranges: 80mV, 800mV, 8V, 80V, 750V

Best Resolution: 1µV

AC Volts Accuracy (80mV, 800mV, 8V ranges):

50/60Hz: ±(0.5% + 10d) 50Hz ~ 1KHz: ±(1.0% +10d) 1KHz ~ 10KHz: ±(3.0% + 10d) 10KHz ~ 20KHz: ±(5.0% + 10d)

AC Volts Accuracy (80V and 750V Range):

1% from 50Hz to 400Hz

AC + DC V Accuracy:  $\pm$ (1.0%+ 10d) 50Hz to 200Hz Max. Input Voltage: 1000 V DC or AC peak Input Impedance:  $10M\Omega$  ( $1G\Omega$  80mV and 800mV)

# DC Current

Ranges: 80mA, 800mA, 8A, 10A; Best Resolution:  $1.0\mu$ A Accuracy:  $\pm (0.5\% + 10d)$ 

Overload Protection: 0.8A/250V fuse and 10A/250V fuse

# AC True RMS Current

Ranges: 80mA, 400mA, 8A, 10A; Best Resolution: 1.0μA Accuracy: ±(0.5% + 10d) 50Hz to 1KHz

Accuracy AC+DC Amps: ±(1.0% + 10d) 50Hz to 200Hz Overload Protection: 800mA/250 fuse and 10A/250V fuse

# DBM

Range: -80dBm to +80dBm; Best Resolution: -0.01dBm

Accuracy: ±(1.0% or reading)

Default Ref impedance is  $600\Omega,$  Ref. Impedances from

 $4\Omega$  to  $1200\Omega$  maybe selected

# Resistance

Ranges:  $800\Omega$ ,  $8K\Omega$ ,  $80K\Omega$ ,  $800K\Omega$ ,  $8M\Omega$ ,  $80M\Omega$ 

Best Resolution: 10.0mΩ; Accuracy: ±(0.3% + 10d) Max. Input Voltage: 250V

# **Diode and Continuity Test**

Range: 8.00V; Accuracy: ±(3% + 10d)

The Buzzer sounds when the measured resistance is  $<50\Omega$ 

# Frequency

Ranges: 1KHz, 10KHz, 100KHz, 100KHz, 8MHz
Best Resolution: 0.01Hz; Input sensitivity: 0.7V AC rms
Accuracy: ±(0.05% + 5d); Max. Input Voltage: 250V
Frequencies to 1Ghz can be read with optional adapter
Secondary display reads: Duty cycle and mS pulse width

# RPN

Range: 0 to 99,999; Resolution: 1RPM

Accuracy: ±(0.1% + 5d)

Note: The RPM function is the secondary display of the frequency measurement and requires the RPM adapter

# Capacitance

Ranges: 1nF, 10nF, 100nF, 1µF, 10µF, 100µF

Best Resolution: 1pF

Accuracy: ±(2.5% + 10d), (±5% + 10d), 1nF range

Maximum Input Volts: 250V

# Temperature

Ranges: -50 to 1372°C (-58 to 2502°F)

Thermocouple: K type

Display: °C primary display °F secondary display

Resolution: 0.1° Accuracy: ±(2.5% + 8d)

# Square wave Generator

Amplitude: Approx 3V

Frequencies from 0.500Hz to 5.000KHz may be selected in

15 Steps

Duty Cycle: Variable from 1% to 99%

# **General Specifications**

Operating Temperature: 0 to 50°C (32 to 122°F) Power: 9Volt battery @ 36 Hours of operation

Size: 7.5" (H) x 3.54" (W) x 1.45" (D)

Weight: 1.43 lbs

Auto Power-Off: 30 minutes or the timer value.

Accessories: Instruction manual, Test leads, Holster,
Temperature probe, 9V battery, RS-232 software and cable

# **Mouser Electronics**

**Authorized Distributor** 

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Protek: 6800